

Gaines Haute Temperature



NOUS POU LONS FABRIQUER SUR MESURE

| | MATERIEL | TEMPERATURE TRAVAIL MAXI. | Ø INTERIEUR | | | | | | | | | | | | | | | | |
|---|------------------------|---------------------------|-------------|---|-----|---|-----|---|-----|---|---|---|---|---|---|----|----|----|----|
| 1 | FIBER-GLASS | 400° | 0,5 | 1 | 1,5 | 2 | 2,5 | 3 | 3,5 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 12 | 14 | 16 |
| 2 | SILICONE | 200° | | | | | | 3 | | | 5 | 6 | 7 | 8 | | | | | |
| 3 | FIBER-GLASS + SILICONE | 220° | 0,5 | 1 | 1,5 | 2 | 2,5 | 3 | 3,5 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 12 | 14 | 16 |

